



Milestone inspection report received: 07/12/2024

Next required inspection report due: 12/31/2034

MARTIN COUNTY MILESTONE INSPECTION REPORT SUMMARY

(A report is required for each building)

This report is based upon Florida State Statute 553.899 - Mandatory structural inspections for condominium and cooperative buildings.

Name of Condo/Co-op: Conquistador Homeowners' Association, Inc.

Address: 1800 SE St. Lucie Blvd., Stuart, FL 34994

Phone: 772-283-2363 Email: Bonnie.Guenther.PM:manager@conquistadorliving.com

Inspecting Firm/Individual Name: Mathers Engineering Corporation

Address: 2411 SE Dixie Hwy., Stuart, FL 34996

Phone Number: (772) 287-0525 Email: office@mathersengineering.com

Inspection Completed Date: March 23, 2023 Building Nos. 1

Inspection Results:

No Repairs Required

Repairs required as outlined in the inspection report but not critical in nature.

Phase 2 Inspection IS or IS NOT required (Check one)

Immediate Repairs Needed - Use of structure should be restricted.

I am qualified to perform the Milestone Inspection in accordance with Florida Statute 553.899.


To the best of my knowledge and ability, this report represents an accurate assessment of the present condition of the structure, based upon careful evaluation of observed conditions, to the extent reasonably possible.

Licensed Engineer/Architect Name: William J. Mathers, P.E.

License Number: PE #19658 / SI #155

Signature: WILLIAM J. MATHERS

Date: 8/15/24



Martin County Building Department - 900 SE Ruhnke Street - Stuart, FL 34994
milestone@martin.fl.us



Milestone inspection report received: 07/12/2024

Next required inspection report due: 12/31/2034

MARTIN COUNTY MILESTONE INSPECTION REPORT SUMMARY

(A report is required for each building)

This report is based upon Florida State Statute 553.899 - Mandatory structural inspections for condominium and cooperative buildings.

Name of Condo/Co-op: Conquistador Homeowners' Association, Inc.

Address: 1800 SE St. Lucie Blvd., Stuart, FL 34994

Phone: 772-283-2363 Email: Bonnie.Guenther.PM:manager@conquestadorliving.com

Inspecting Firm/Individual Name: Mathers Engineering Corporation

Address: 2411 SE Dixie Hwy., Stuart, FL 34996

Phone Number: (772) 287-0525 Email: office@mathersengineering.com

Inspection Completed Date: March 23, 2023 Building Nos. 2

Inspection Results:

No Repairs Required

Repairs required as outlined in the inspection report but not critical in nature.

Phase 2 Inspection IS or IS NOT required (Check one)

Immediate Repairs Needed - Use of structure should be restricted.

I am qualified to perform the Milestone Inspection in accordance with Florida Statute 553.899.


To the best of my knowledge and ability, this report represents an accurate assessment of the present condition of the structure, based upon careful evaluation of observed conditions, to the extent reasonably possible.

Licensed Engineer/Architect Name: William J. Mathers, P.E.

License Number: PE #19658 / SI #155

Signature: W. J. Mathers

Date: 8/15/23



Martin County Building Department - 900 SE Ruhnke Street - Stuart, FL 34994
milestone@martin.fl.us



Milestone inspection report received: 07/12/2024

Next required inspection report due: 12/31/2024

MARTIN COUNTY MILESTONE INSPECTION REPORT SUMMARY

(A report is required for each building)

This report is based upon Florida State Statute 553.899 - Mandatory structural inspections for condominium and cooperative buildings.

Name of Condo/Co-op: Conquistador Homeowners' Association, Inc.

Address: 1800 SE St. Lucie Blvd., Stuart, FL 34994

Phone: 772-283-2363 Email: Bonnie.Guenther.PM:manager@conquistadorliving.com

Inspecting Firm/Individual Name: Mathers Engineering Corporation

Address: 2411 SE Dixie Hwy., Stuart, FL 34996

Phone Number: (772) 287-0525 Email: office@mathersengineering.com

Inspection Completed Date: March 23, 2023 Building Nos. 3

Inspection Results:

No Repairs Required

Repairs required as outlined in the inspection report but not critical in nature.

Phase 2 inspection IS or IS NOT required (Check one)

Immediate Repairs Needed - Use of structure should be restricted.

I am qualified to perform the Milestone Inspection in accordance with Florida Statute 553.899.


To the best of my knowledge and ability, this report represents an accurate assessment of the present condition of the structure, based upon careful evaluation of observed conditions, to the extent reasonably possible.

Licensed Engineer/Architect Name: William J. Mathers, P.E.

License Number: PE #19658 / SI #155

Signature: W. J. Mathers

Date: 8/15/2024



Martin County Building Department - 900 SE Ruhnke Street - Stuart, FL 34994
milestone@martin.fl.us



Milestone inspection report received: 07/12/2024

Next required inspection report due: 12/31/2034

MARTIN COUNTY MILESTONE INSPECTION REPORT SUMMARY

(A report is required for each building)

This report is based upon Florida State Statute 553.899 - Mandatory structural inspections for condominium and cooperative buildings.

Name of Condo/Co-op: Conquistador Homeowners' Association, Inc.

Address: 1800 SE St. Lucie Blvd., Stuart, FL 34994

Phone: 772-283-2363 Email: Bonnie Guenther PM:manager@conquistadorliving.com

Inspecting Firm/Individual Name: Mathers Engineering Corporation

Address: 2411 SE Dixie Hwy., Stuart, FL 34996

Phone Number: (772) 287-0525 Email: office@mathersengineering.com

Inspection Completed Date: March 23, 2023 Building Nos. 4

Inspection Results:

No Repairs Required

Repairs required as outlined in the inspection report but not critical in nature.

Phase 2 Inspection IS or IS NOT required (Check one)

Immediate Repairs Needed - Use of structure should be restricted.

I am qualified to perform the Milestone Inspection in accordance with Florida Statute 553.899.


To the best of my knowledge and ability, this report represents an accurate assessment of the present condition of the structure, based upon careful evaluation of observed conditions, to the extent reasonably possible.

Licensed Engineer/Architect Name: William J. Mathers, P.E.

License Number: PE #19658 / SI #155

Signature: W. J. Mathers

Date: 8/15/24



Martin County Building Department - 900 SE Rutledge Street - Stuart, FL 34994
milestone@martin.fl.us



Milestone inspection report received: 07/12/2024

Next required inspection report due: 12/31/2034

MARTIN COUNTY MILESTONE INSPECTION REPORT SUMMARY

(A report is required for each building)

This report is based upon Florida State Statute 553.899 - Mandatory structural inspections for condominium and cooperative buildings.

Name of Condo/Co-op: Conquistador Homeowners' Association, Inc.

Address: 1800 SE St. Lucie Blvd., Stuart, FL 34994

Phone: 772-283-2363 Email: Bonnie.Guenther.PM:manager@conquistadorliving.com

Inspecting Firm/Individual Name: Mathers Engineering Corporation

Address: 2411 SE Dixie Hwy., Stuart, FL 34996

Phone Number: (772) 287-0525 Email: office@mathersengineering.com

Inspection Completed Date: March 23, 2023 Building Nos. 5

Inspection Results:

No Repairs Required

Repairs required as outlined in the inspection report but not critical in nature.

Phase 2 Inspection IS or IS NOT required (Check one)

Immediate Repairs Needed - Use of structure should be restricted.

I am qualified to perform the Milestone Inspection in accordance with Florida Statute 553.899.


To the best of my knowledge and ability, this report represents an accurate assessment of the present condition of the structure, based upon careful evaluation of observed conditions, to the extent reasonably possible.

Licensed Engineer/Architect Name: William J. Mathers, P.E.

License Number: PE #19658 / SI #155

Signature: W. J. Mathers

Date: 8/15/24



Send to:

Martin County Building Department - 900 SE Ruhne Street - Stuart, FL 34994
milestone@martin.fl.us



Milestone inspection report received: 07/12/2024

Next required inspection report due: 12/31/2024

MARTIN COUNTY MILESTONE INSPECTION REPORT SUMMARY

(A report is required for each building)

This report is based upon Florida State Statute 553.899 - Mandatory structural inspections for condominium and cooperative buildings.

Name of Condo/Co-op: Conquistador Homeowners' Association, Inc.

Address: 1800 SE St. Lucie Blvd., Stuart, FL 34994

Phone: 772-283-2363 Email: Bonnie.Guenther.PM:manager@conquistadorliving.com

Inspecting Firm/Individual Name: Mathers Engineering Corporation

Address: 2411 SE Dixie Hwy., Stuart, FL 34996

Phone Number: (772) 287-0525 Email: office@mathersengineering.com

Inspection Completed Date: March 23, 2023 Building Nos. 6

Inspection Results:

No Repairs Required

Repairs required as outlined in the inspection report but not critical in nature.

Phase 2 Inspection IS or IS NOT required (Check one)

Immediate Repairs Needed - Use of structure should be restricted.

I am qualified to perform the Milestone Inspection in accordance with Florida Statute 553.899.


To the best of my knowledge and ability, this report represents an accurate assessment of the present condition of the structure, based upon careful evaluation of observed conditions, to the extent reasonably possible.

Licensed Engineer/Architect Name: William J. Mathers, P.E.

License Number: PE #19658 / SI #155

Signature: William J. Mathers

Date: 8/15/24



Martin County Building Department - 900 SE Ruhpke Street - Stuart, FL 34994
milestone@martin.fl.us



Milestone inspection report received: 07/12/2024

Next required inspection report due: 12/31/2034

MARTIN COUNTY MILESTONE INSPECTION REPORT SUMMARY

(A report is required for each building)

This report is based upon Florida State Statute 553.899 - Mandatory structural inspections for condominium and cooperative buildings.

Name of Condo/Co-op: Conquistador Homeowners' Association, Inc.

Address: 1800 SE St. Lucie Blvd., Stuart, FL 34994

Phone: 772-283-2363 Email: Bonnie.Guenther.PM:manager@conquistadorliving.com

Inspecting Firm/Individual Name: Mathers Engineering Corporation

Address: 2411 SE Dixie Hwy., Stuart, FL 34996

Phone Number: (772) 287-0525 Email: office@mathersengineering.com

Inspection Completed Date: March 23, 2023 Building Nos. 7

Inspection Results:

No Repairs Required

Repairs required as outlined in the inspection report but not critical in nature.

Phase 2 Inspection IS or IS NOT required (Check one)

Immediate Repairs Needed - Use of structure should be restricted.

I am qualified to perform the Milestone Inspection in accordance with Florida Statute 553.899.


To the best of my knowledge and ability, this report represents an accurate assessment of the present condition of the structure, based upon careful evaluation of observed conditions, to the extent reasonably possible.

Licensed Engineer/Architect Name: William J. Mathers, P.E.

License Number: PE #19658 / SI #155

Signature: Wm J Mathers

Date: 8/15/2023



Martin County Building Department - 900 SE Ruhnke Street - Stuart, FL 34994
milestone@martin.fl.us



Milestone inspection report received: 07/12/2024

Next required inspection report due: 12/31/2034

MARTIN COUNTY MILESTONE INSPECTION REPORT SUMMARY

(A report is required for each building)

This report is based upon Florida State Statute 553.899 - Mandatory structural inspections for condominium and cooperative buildings.

Name of Condo/Co-op: Conquistador Homeowners' Association, Inc.

Address: 1800 SE St. Lucie Blvd., Stuart, FL 34994

Phone: 772-283-2363 Email: Bonnie.Guenther.PM:manager@conquistadorliving.com

Inspecting Firm/Individual Name: Mathers Engineering Corporation

Address: 2411 SE Dixie Hwy., Stuart, FL 34996

Phone Number: (772) 287-0525 Email: office@mathersengineering.com

Inspection Completed Date: March 23, 2023 Building Nos. 8

Inspection Results:

No Repairs Required

Repairs required as outlined in the inspection report but not critical in nature.

Phase 2 Inspection IS or IS NOT required (Check one)

Immediate Repairs Needed - Use of structure should be restricted.

I am qualified to perform the Milestone Inspection in accordance with Florida Statute 553.899.


To the best of my knowledge and ability, this report represents an accurate assessment of the present condition of the structure, based upon careful evaluation of observed conditions, to the extent reasonably possible.

Licensed Engineer/Architect Name: William J. Mathers, P.E.

License Number: PE #19658 / SI #155

Signature: W.J. Mathers

Date: 8/15/24



Martin County Building Department - 900 SE Ruhnke Street - Stuart, FL 34994
milestone@martin.fl.us



Milestone inspection report received: 07/12/2024

Next required inspection report due: 12/31/2034

MARTIN COUNTY MILESTONE INSPECTION REPORT SUMMARY

(A report is required for each building)

This report is based upon Florida State Statute 553.899 - Mandatory structural inspections for condominium and cooperative buildings.

Name of Condo/Co-op: Conquistador Homeowners' Association, Inc.

Address: 1800 SE St. Lucie Blvd., Stuart, FL 34994

Phone: 772-283-2363 Email: Bonnie.Guenther.PM:manager@conquistadorliving.com

Inspecting Firm/Individual Name: Mathers Engineering Corporation

Address: 2411 SE Dixie Hwy., Stuart, FL 34996

Phone Number: (772) 287-0525 Email: office@mathersengineering.com

Inspection Completed Date: March 23, 2023 Building Nos. 9

Inspection Results:

No Repairs Required

Repairs required as outlined in the inspection report but not critical in nature.

Phase 2 Inspection IS or IS NOT required (Check one)

Immediate Repairs Needed - Use of structure should be restricted.

I am qualified to perform the Milestone Inspection in accordance with Florida Statute 553.899.


To the best of my knowledge and ability, this report represents an accurate assessment of the present condition of the structure, based upon careful evaluation of observed conditions, to the extent reasonably possible.

Licensed Engineer/Architect Name: William J. Mathers, P.E.

License Number: PE #19658 / SI #155

Signature: WJM

Date: 8/15/24



Martin County Building Department - 900 SE Ruhnke Street - Stuart, FL 34994
milestone@martin.fl.us



Milestone inspection report received: 07/12/2024

Next required inspection report due: 12/31/2024

MARTIN COUNTY MILESTONE INSPECTION REPORT SUMMARY

(A report is required for each building)

This report is based upon Florida State Statute 553.899 - Mandatory structural inspections for condominium and cooperative buildings.

Name of Condo/Co-op: Conquistador Homeowners' Association, Inc.

Address: 1800 SE St. Lucie Blvd., Stuart, FL 34994

Phone: 772-283-2363 Email: Bonnie.Guenther.PM:manager@conquistadorliving.com

Inspecting Firm/Individual Name: Mathers Engineering Corporation

Address: 2411 SE Dixie Hwy., Stuart, FL 34996

Phone Number: (772) 287-0525 Email: office@mathersengineering.com

Inspection Completed Date: March 23, 2023 Building Nos. 10

Inspection Results:

No Repairs Required

Repairs required as outlined in the inspection report but not critical in nature.

Phase 2 Inspection IS or IS NOT required (Check one)

Immediate Repairs Needed - Use of structure should be restricted.

I am qualified to perform the Milestone Inspection in accordance with Florida Statute 553.899.


To the best of my knowledge and ability, this report represents an accurate assessment of the present condition of the structure, based upon careful evaluation of observed conditions, to the extent reasonably possible.

Licensed Engineer/Architect Name: William J. Mathers, P.E.

License Number: PE #19658 / SI #155

Signature: W. J. Mathers

Date: 8/15/2024



Martin County Building Department - 900 SE RUHMKER Street - Stuart, FL 34994
milestone@martin.fl.us



Milestone inspection report received: 07/12/2024

Next required inspection report due: 12/31/2034

MARTIN COUNTY MILESTONE INSPECTION REPORT SUMMARY

(A report is required for each building)

This report is based upon Florida State Statute 553.899 - Mandatory structural inspections for condominium and cooperative buildings.

Name of Condo/Co-op: Conquistador Homeowners' Association, Inc.

Address: 1800 SE St. Lucie Blvd., Stuart, FL 34994

Phone: 772-283-2363 Email: Bonnie.Guenther.PM:manager@conquistadorliving.com

Inspecting Firm/Individual Name: Mathers Engineering Corporation

Address: 2411 SE Dixie Hwy., Stuart, FL 34996

Phone Number: (772) 287-0525 Email: office@mathersengineering.com

Inspection Completed Date: March 23, 2023 Building Nos. 11

Inspection Results:

No Repairs Required

Repairs required as outlined in the inspection report but not critical in nature.

Phase 2 Inspection IS or IS NOT required (Check one)

Immediate Repairs Needed - Use of structure should be restricted.

I am qualified to perform the Milestone Inspection in accordance with Florida Statute 553.899.


To the best of my knowledge and ability, this report represents an accurate assessment of the present condition of the structure, based upon careful evaluation of observed conditions, to the extent reasonably possible.

Licensed Engineer/Architect Name: William J. Mathers, P.E.

License Number: PE #19658 / SI #155

Signature: William J. Mathers

Date: 8/15/24



Martin County Building Department - 900 SE Ruhnke Street - Stuart, FL 34994
milestone@martin.fl.us



Milestone inspection report received: 07/12/2024

Next required inspection report due: 12/31/2034

MARTIN COUNTY MILESTONE INSPECTION REPORT SUMMARY

(A report is required for each building)

This report is based upon Florida State Statute 553.899 - Mandatory structural inspections for condominium and cooperative buildings.

Name of Condo/Co-op: Conquistador Homeowners' Association, Inc.

Address: 1800 SE St. Lucie Blvd., Stuart, FL 34994

Phone: 772-283-2363 Email: Bonnie.Guenther.PM:manager@conquistadorliving.com

Inspecting Firm/Individual Name: Mathers Engineering Corporation

Address: 2411 SE Dixie Hwy., Stuart, FL 34996

Phone Number: (772) 287-0525 Email: office@mathersengineering.com

Inspection Completed Date: March 23, 2023 Building Nos. 12

Inspection Results:

No Repairs Required

Repairs required as outlined in the inspection report but not critical in nature.

Phase 2 Inspection IS or IS NOT required (Check one)

Immediate Repairs Needed - Use of structure should be restricted.

I am qualified to perform the Milestone Inspection in accordance with Florida Statute 553.899.


To the best of my knowledge and ability, this report represents an accurate assessment of the present condition of the structure, based upon careful evaluation of observed conditions, to the extent reasonably possible.

Licensed Engineer/Architect Name: William J. Mathers, P.E.

License Number: PE #19658 / SI #155

Signature: W. J. Mathers

Date: 9/15/24



Martin County Building Department, 1800 SE St. Lucie Street - Stuart, FL 34994
milestone@martin.fl.us